

IRRIGATION REPORT

Property: **2213 - The Soundings HOA**

Date of Inspection/ Onsite Repairs: **08/25/25**

#Clock (s): **1**

Clock Approx. Location: **Side of The House**

of Zones: **4**

Clock Start Time: **4 AM**

Watering Days: **W - Sun**



Monthly Scheduled Inspection



Client Requested Visit



Estimate For Repairs



Repairs Performed



Check & Adjustments Only

Our Results & Findings

Work Order: This is your Quarterly Inspection. **NO CHANGE FROM PREVIOUS REPORT.**

Notes/ Findings: When the Irrigation techs arrived onsite, they noticed the Clock was on the "OFF" position. They turned it on, so they were able to see if it was damaged at all or not. Your Clock and Pump are functioning properly. The techs cleaned and adjusted the sprinklers. They did see 3x 4" Broken 4" Spray heads and 3x Nozzles, on the side of the house. Everything is functioning properly. They left the clock on "OFF" position, just as we found it. Once **"Approved"**, they will be back out to complete it. Please let me know how you would like to proceed. 😊

Breakdown of Repairs for Approved Request.

3x 4" Spray Head

3x Spray Nozzles

Repairs

Fresh Start Maintenance Inc.

Irrigation director:

Ms. Yolande Saintil

Admin2@FreshStartMaintenance.com

Office: 1.844.307.2319 or 561.308.2773

Price. \$135.00

QUICKBOOKS INVOICE #