

IRRIGATION REPORT

Property: **2231 - The Soundings HOA**

Date of Inspection/ Onsite Repairs: **08/25/25**

#Clock (s): **1**

Clock Approx. Location: **Side of The House**

of Zones: **4**

Clock Start Time: **3 AM**

Watering Days: **M - W - Sat**



Monthly Scheduled Inspection



Client Requested Visit



Estimate For Repairs



Repairs Performed



Check & Adjustments Only

Our Results & Findings

Work Order: This is your Quarterly Inspection.

TECHS NOTED THE HOMEOWNERS NO LONGER LIVE HERE. ... NO CHANGE TO REPORT.

Notes/ Findings: The technicians were onsite, and your Clock was on the "OFF" position. The techs have noted that you have a "BIG BREAK" under the tree by the roots. Our techs have noted the breaks have gotten worse from not doing any repairs from the previous report from 02/17/25. Your Solenoid needs to be replaced. The back has a broken PVC Pipe - 1 1/4". On the side of the house, you have a broken Sprinkler - 4" Spray Head. Below are just Estimates, we just need the "Approval" to complete the work.

Breakdown of Repairs for Approved Request.

4x PVC Pipe

4x 3/4 Barbed 90's

1x 4" Spray head

1x Solenoid

Repairs

Fresh Start Maintenance Inc.

Irrigation Director:

Ms. Yolande Saintil

Admin2@FreshStartMaintenance.com

Office: 1.844.307.2319 or 561.308.2773

Price. \$307.00

QUICKBOOKS INVOICE #